




I、 components description




II、 Tools prepare




III、 Strip cable and coating



IV、 Cutting the fiber (different cutting tool may differ, please refer to the size label on the box)



V、 Pull the fiber through and clamp it




VI、 Fix the fiber(must be sequented by step 1 2 3)



VII、 clean the fiber end, check the end results, drop some matching liquid on the end

Clean the end with a absolute alcohol moistened clean paper, clean it softly up and down as the arrow direction in this pic, please never radial wipe the end which can damage the fiber end seriously



VIII、 unload steps



If you experience any issues using these fiber connectors, please contact FIBER·TRONIX Tech Support: (610) 428-1921