


I、 components description




II、 Tools prepare



III、 Stripping cable and coating and mounted fiber optic cable clamp



IV、 Cutting the fiber (different cutting tool may differ, please refer to the size label on the box)



V、 Pull the fiber through and clamp it




VI、 Fix the fiber (must be sequented by step 1 2 3)



VII、 clean the fiber end, check the end results, drop some matching liquid on the end

Clean the ferrule with the professional fiber cleaner, press lightly according to the arrow. Avoid overexertion damage the end.



VIII、 unload steps

1. loose the fiber clamp (be careful : hold the click softly by your finger) 2. loose the cable clamp



If you experience any issues using these fiber connectors, please contact FIBER·TRONIX Tech Support: (610) 428-1921